






















MBD100/200/300




MBD100E/200E/300E





MBD100/200/300




ZLBM.../ZHBM...




A




3-9



MBD100E/200E/300E



ZHBM + EFM





B



**3
10-16**


A

ZLBM..




T30
6 Nm

ZHBM..









B



ZHBM.. + EFM






T30
6 Nm













	CU 30x10	CU 40x10
		
MBD100	ZX1220	ZX1226
MBD200	ZX1221	ZX1227
MBD300	ZX1222	ZX1228




M8
SW13
10 Nm



M12
SW18
25 Nm










	Type	A	B	C	D
MBD100	AG243	25,25	199,5	-	-
MBD200	AG244	50,25	399,5	-	-
MBD300	AG245	50,25	299,5	50,5	299,5














	CU 30x10	CU 40x10
		
MBD100E	ZX1220	ZX1226
MBD200E	ZX1221	ZX1227
MBD300E	ZX1222	ZX1228







		I			II		
	Type	A	B	C	A	B	C
MBD100E	AG246	25,25	199,5	85	25,25	199,5	52,5
MBD200E	AG247	50,25	399,5	85	50,25	399,5	52,5
MBD300E	AG248	50,25	649,5	85	50,25	649,5	52,5





	CU 30x10 	CU 40x10 
MBD200 (E) + MBD200 (E)	ZX1220	ZX1226
MBD300 (E) + MBD200 (E)	ZX1221	ZX1227
MBD300 (E) + MBD300 (E)	ZX1222	ZX1228